



Southeastern Area • 453 S. Carbon Avenue • P.O. Box 718 • Price, UT 84501-0718 • 801-637-1303

May 17, 1990

Stowell Mutual Water Company Attn: David Rowley, President Rt. 1 Box 73 Helper, Utah 84526

Re: Parshall Flume Measuring Device

Dear Dave:

As we have discussed on several occasions in the past few days, the parshall flume measuring device in the Stowell Ditch is not functioning properly, and as a result, the water in the ditch cannot be accurately measured. It appears that there is some reservation on the part of the Company to take care of this matter.

Therefore, this letter is written to initiate Agency action concerning this matter, which is in violation of Section 73-5-4 Utah Code Annotated 1953, as amended, which requires each person using water in this state to construct, install and maintain measuring devices for the purpose of regulating the quantity of water that may be diverted. In accordance with this same Section, you are hereby requested to remedy this matter in such a fashion that the water in the Stowell Ditch can be completely and adequately measured. This should be accomplished within 30 days of the date hereof. Please notify this office when this has been completed, so that your compliance to this action can be verified. Your failure to comply with this request will result in further legal action by this Division.

If you have any questions concerning this letter or its contents, please feel free to contact me. Your immediate response will be appreciated.

Sincerely,

Mark P. Page Area Engineer

Certified Mail MPP/mjk